

National Transportation Safety Board
Washington, DC 20594

Printed on : 2/17/2013 3:44:06 PM

Brief of Accident

Adopted 11/29/2007

DCA06MA009 File No. 22717	12/08/2005	Chicago, IL	Aircraft Reg No. N471WN	Time (Local): 19:15 CST		
Make/Model:	Boeing / 737-700			Fatal	Serious	Minor/None
Engine Make/Model:	Cfm International / 56-7B24		Crew	0	0	5
Aircraft Damage:	Substantial		Pass	0	0	98
Number of Engines:	2		Other	1	1	3
Operating Certificate(s):	Flag Carrier/Domestic					
Name of Carrier:	SOUTHWEST AIRLINES CO					
Type of Flight Operation:	Scheduled; Domestic; Passenger Only					
Reg. Flight Conducted Under:	Part 121: Air Carrier					
Last Depart. Point:	Baltimore, MD			Condition of Light:	Night	
Destination:	Same as Accident/Incident Location			Weather Info Src:	Weather Observation Facility	
Airport Proximity:	On Airport/Airstrip			Basic Weather:	Instrument Conditions	
Airport Name:	Midway Airport			Lowest Ceiling:	Obscured	
Runway Identification:	31C			Visibility:		
Runway Length/Width (Ft):	6522 / 150			Wind Dir/Speed:	110 / 007 Kts	
Runway Surface:	Concrete			Temperature (°C):	-4	
Runway Surface Condition:	Snow			Precip/Obscuration:	Moderate - Showers - Snow	
Pilot-in-Command	Age: 59			Flight Time (Hours)		
Certificate(s)/Rating(s)				Total All Aircraft:	8500	
Airline Transport; Multi-engine Land				Last 90 Days:	243	
Instrument Ratings				Total Make/Model:	6000	
Airplane				Total Instrument Time:	UnK/Nr	

*** Note: NTSB investigators traveled in support of this investigation and used data obtained from various sources to prepare this aircraft accident report. ***

The Safety Board's full report is available at <http://www.nts.gov/publicn/publicn.htm>. The Aircraft Accident Brief number is NTSB/AAR-07/06.

On December 8, 2005, about 1914 central standard time, Southwest Airlines (SWA) flight 1248, a Boeing 737-7H4, N471WN, ran off the departure end of runway 31 center (31C) after landing at Chicago Midway Airport (MDW), Chicago, Illinois. The airplane rolled through a blast fence, and airport perimeter fence, and onto an adjacent roadway, where it struck an automobile before coming to a stop. A child in the automobile was killed, one automobile occupant received serious injuries, and three other automobile occupants received minor injuries. Eighteen of the 103 airplane occupants (88 passengers, 3 flight attendants, and 2 pilots) received minor injuries, and the airplane was substantially damaged. The airplane was being operated under the provisions of 14 Code of Federal Regulations (CFR) Part 121 and had departed from Baltimore/Washington International Thurgood Marshall Airport (BWI), Baltimore, Maryland, about 1758 eastern standard time. Instrument meteorological conditions prevailed at the time of the accident flight, which operated on an instrument flight rules flight plan.

Brief of Accident (Continued)

DCA06MA009				
File No. 22717	12/08/2005	Chicago, IL	Aircraft Reg No. N471WN	Time (Local): 19:15 CST

Occurrence #1: OVERRUN
Phase of Operation: LANDING - ROLL

Findings

1. (C) THRUST REVERSER - INADEQUATE
2. (C) PROCEDURES/DIRECTIVES - NOT FOLLOWED - FLIGHTCREW
3. (C) LACK OF FAMILIARITY WITH AIRCRAFT - FLIGHTCREW
4. (F) PROCEDURE INADEQUATE
5. (F) CONDITION(S)/STEP(S) INSUFFICIENTLY DEFINED - COMPANY/OPERATOR MANAGEMENT

Occurrence #2: ON GROUND/WATER COLLISION WITH OBJECT
Phase of Operation: LANDING - ROLL

Findings

6. OBJECT - FENCE
7. OBJECT - VEHICLE

Findings Legend: (C) = Cause, (F) = Factor

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilots' failure to use available reverse thrust in a timely manner to safely slow or stop the airplane after landing, which resulted in a runway overrun. This failure occurred because the pilots' first experience and lack of familiarity with the airplane's autobrake system distracted them from thrust reverser usage during the challenging landing.

Contributing to the accident were Southwest Airline's 1) failure to provide its pilots with clear and consistent guidance and training regarding company policies and procedures related to arrival landing distance calculations; 2) programming and design of its onboard performance computer, which did not present inherent assumptions in the program critical to pilot decision making; 3) plan to implement new autobrake procedures without a familiarization period; and 4) failure to include a margin of safety in the arrival assessment to account for operational uncertainties. Also contributing to the accident was the pilots' failure to divert to another airport given reports that included poor braking action and a tailwind component greater than 5 knots. Contributing to the severity of the accident was the absence of an engineering materials arresting system, which was needed because of the limited runway safety area beyond the departure end of runway 31C.